



WORLD HEADQUARTERS • BENTON HARBOR, MICHIGAN 49022-2692

Dear Valued Customer:

High Voltage Board Part Numbers W10581605, W10583022, & W10603638

This special handling letter is for High Voltage board replacement for the below list of French door bottom mount refrigerators. Due to a quality issues, service kits have been created to include both the Dispenser User Interface assembly and High Voltage board to solve the double fill issues.

Therefore, any product requiring a replacement of one of the above parts will need to order one of the service kits according to model number. Refer to list below.

Sincerely,

Whirlpool Corporation
Consumer and Appliance Care

Model Number	Service Kit	Model Number	Service Kit
KFIS29BBBL00	W10637196	WRF736SDAB10	W10639152
KFIS29BBBL01	W10639153	WRF736SDAF10	W10639151
KFIS29BBMS00	W10637199	WRF736SDAM10	W10639151
KFIS29BBMS01	W10639165	WRF736SDAW10	W10639151
KFIS29BBWH00	W10637199	WRF989SDAB00	W10639001
KFIS29BBWH01	W10639165	WRF989SDAB01	W10639184
KFIS29PBMS00	W10637219	WRF989SDAE00	W10639002
KFIS29PBMS01	W10639166	WRF989SDAE01	W10639750
KFIV29PCMS00	W10637219	WRF989SDAF00	W10639002
KFIV29PCMS01	W10639166	WRF989SDAF01	W10639750
MFT2672AEB10	W10639092	WRF989SDAH00	W10639002
MFT2672AEM10	W10639093	WRF989SDAH01	W10639750
MFT2672AEW10	W10639094	WRF989SDAM00	W10639002

MFT2673BEB10	W10639092	WRF989SDAM01	W10639750
MFT2673BEM10	W10639093	WRF989SDAW00	W10639002
MFT2673BEW10	W10639094	WRF989SDAW01	W10639750
MFT2976AEB00	W10639181	WRF990SLAB00	W10639753
MFT2976AEB01	W10639181	WRF990SLAM00	W10639004
MFT2976AEM00	W10639168	WRF990SLAM01	W10639751
MFT2976AEM01	W10639168	7WF736SDAM10	W10639151
MFT2976AEW00	W10639183		
MFT2976AEW01	W10639183		
7MF2976AEM00	W10639168		
7MF2976AEM01	W10639168		